OMRON

Smart Fiber Sensor E3X-HD Series

INSTRUCTION SHEET

Thank you for selecting an OMRON product. This sheet required in installing and operating the product.

- · A specialist who has the knowledge of electricity must treat the product.
- Please read this manual carefully, and use it correctly after
- thoroughly understanding the product. • Please keep this manual properly for future reference whenever it is necessary.



© OMRON Corporation 2011 All Rights Reserved

PRECAUTIONS ON SAFETY

Meanings of Signal Words



Indicates a potentially hazardous situation which, if not avoided, may result in minor or moderate injury or in property damage.

Warning Indications

/ PRECAUTIONS

Do not use the product with voltage in excess of the rated voltage. Excess voltage may result in malfunction or fire.



Never use the product with an AC power supply. Otherwise, explosion may result


PRECAUTIONS FOR SAFE USE

The following precautions must be observed to ensure safe operation of the Sensor.

- Do not use the Sensor in environments subject to flammable or explosive gases.
- Do not use the Sensor in environments subject to exposure to water, oil, chemicals, etc. · Do not install the Sensor in environments subject to intense electric field or ferromagnetic field.
- · Do not attempt to disassemble, repair, or modify the Sensor Unit in any way.
- Do not apply voltages or currents that exceed the rated ranges.
- · Do not use the Sensor in any atmosphere or environment that exceeds the ratings.
- · Do not miswire such as the polarity of the power supply.
- · Connect the load correctly
- · Do not short both ends of the load
- Do not use the Sensor if the case is damaged. · When disposing of the Sensor,treat it as industrial waste.
- · Burn injury may occur. The Sensor surface temperature rises depending on application conditions, such as the
- ambient temperature and the power supply voltage. Use caution when operating or cleaning the Sensor High-Voltage lines and power lines must be wired separately from this product. Wiring them together or placing them in the same duct may cause induction, resulting in malfunction or damage.
- · When setting the Sensor, be sure to check safety such as by stopping the equipment.

PRECAUTIONS FOR CORRECT USE

- Do not install the Sensor in the following locations.
- (1) Locations subject to direct sunlight
- (2) Locations subject to condensation due to high humidity
- (3) Locations subject to corrosive gas
- (4) Locations subject to vibration or mechanical shocks exceeding the rated values
- Use an extension cable with a minimum thickness of 0.3 mm2 and less than 100 m long. · Do not apply the forces on the cord exceeding the following limits:
- Pull: 40N: torque: 0.1N·m: pressure: 20N: bending: 3 kg
- The Sensor is ready to operate 200 ms after the power supply is turned ON. If the Sensor and load are connected to power supplies separately, turn ON the power supply to the Sensor first.
- When using a connector type product, place a protective label (provided with the E3X-CN series connectors) on the power supply connecting terminals that are not used, to prevent electric shock or short




- Output pulses may occur when the power supply is turned OFF. Turn OFF the power supply to the load
- Excessive incident light cannot be sufficiently handled by the mutual interference prevention function and may cause malfunction. To prevent this, set a higher threshold level.
- Make sure that the power supply is turned OFF before connecting, separating or adding Amplifier Units. Do not pull or apply excessive pressure or force (exceeding 9.8N) on the Fiber Unit when it is mounted
- The E3X-MC11-SV2 and E3X-MC11-S Mobile Consoles cannot be used.
- Mutual interference prevention does not function among the E3X-DA-N/SD/NA amplifiers. It functions among E3X-DA-S/MDA models.
- The E3X-DRT21-S, E3X-CRT and E3X-ECT Communication Units cannot be used. Always keep the protective cover in place when using the Amplifier Unit
- Dor not use thinner, benzine, acetone, and lamp oil for cleaning

Checking the Package Content • Amplifier Unit: 1 • Instruction Sheet (this sheet): 1 (Japanese, English and Chinese)

1 Installation

1-1 Dimensions



1-2 Mounting the Amplifier Unit

■ Mounting on DIN Track

1. Let the hook on the Amplifier Unit's Fiber Unit connection side catch the track and push the unit until it clicks.

■ Removing from DIN Track


- 1. Push the unit in the direction 1.
- 2. Lift it up in the direction 2.



Refer to "1-1. Dimensions" or check the side of the unit for wire color and role indications

■ Mounting Amplifier Units in Group (Connector Type Models)

- 1. Mount the Amplifier Units one at a time onto the DIN track and push them until they click. Use E3X-CN11 (Master connector) for the master Amplifier Unit and E3X-CN12 (Slave connector) for the slave Amplifier Units.
- 2. Slide the Amplifier Units in the direction 2.
- 3 Use End Plates (PFP-M: separately sold) at the both ends of the grouped Amplifier Units to prevent them from separating due to vibration or other cause.
- 4. Tighten the screw on the End Plates using a driver.



1-3 Mounting Fiber Unit

■ Use Fiber Cutter

1. Insert a Fiber Unit into a fiber cutter hole. Insert a standard Fiber Unit up to the position in which it is cut; and a thin-diameter Fiber Unit to the bottom of the hole.

2. Press down the blade at a single stroke to cut the Fiber Unit.

■ Mount Fiber Unit

- Open the protective cover.
- 2. Raise the lock lever.
- 3. Insert the Fiber Unit in the fiber unit hole to the bottom
- 4. Return the lock lever to the original position and fix the Fiber Unit.
- When mounting a coaxial reflective Fiber Unit insert the single-core Fiber Unit to the upper hole (Emitter side) and the multi-core Fiber Unit to the lower hole (Receiver side).




Fiber Unit Connection Side Hook





2-1 Setting and Display Overview

2 Settings




2-2 Switching Control Output




[L/D Indicator] turns D ON.

Reflective: Set to "Light ON" to turn the output ON with a workpiece in the detection area

output ON with a workpiece in the detection area





2-3 Smart Tuning [Easy Sensitivity Setting]

1 Detect for Workpiece Presence/Absence

2-point Tuning


1. Press button with a workpiece in the detection area.





2. Press button again without a workpiece in the detection area.






Incident light level setting: The larger incident level of the Step 1 and 2 values is adjusted to the power tuning level. Threshold setting: Set to the middle between the Step 1 and 2 incident light levels.

Step 1 and Step 2 can be reversed.

2 Detect for Workpiece Presence/Absence

- Maximum Sensitivity Tuning
- 1. Hold button for 3 seconds or longer with/without workpiece as shown below. Release the button when [5L FULL] is displayed. Through-beam: Workpiece is present








Threshold setting: The value is set to approx. 7% of the incident light level of 1. If the incident light level of 1 is smaller during long distance detection, the minimum value by which an output is correctly turned ON will be set.

(3) Adjust for Moving Workpiece without Stopping Line

Full Auto Tuning

1. Hold the button without the presence of a workpiece, and pass the workpiece through while [IPnL] -> [FULL] -> [AULo] is displayed in red digital. (Keep holding the button while the workpiece passes through, and hold 7 seconds or longer until [AULo] is displayed in red digital. After the workpiece passes through, release your finger from the o button.)



Incident light level setting: Adjust the max. incident light level on Step 1 as the power tuning level. Threshold setting: Set to the middle between max. and min. incident light levels on Step 1.

4 Determine Workpiece Position

Position Tuning

1. Press button without a workpiece in the area.



Hold for 3 seconds or longer The red digital display changes $[\partial^{\rho} \cap b] \rightarrow [\rho_{\alpha} S]$.

Setting is Completed


Incident light level setting: The Step 2 incident level is adjusted to half the power tuning level. Threshold setting: Set to the same value as the Step 2 incident level.

(5) Detect Transparent or Small Workpiece (Set Threshold by incident light level percentage)

Percentage Tuning

1. Turn ON Percentage Tuning in SET mode. Refer to " 5 Detailed Settings".

2. Press button without a workpiece in the area.



Incident light level setting: The Step 2 incident light level is adjusted to the

Threshold setting: Set to the value obtained by [Incident Level at Step 2 x Percentage Tuning Level + Incident Level at Step 2].

No Smart Tuning other than Power Tuning can be used if Percentage Tuning is set.

Smart Tuning Error

Error / Display / Cause	Error Origin Tuning Type	Remedy
Near Error The light level difference between Points 1 and 2 are extremely small.	2-point Tuning Full Auto Tuning Positioning Tuning	Change the detection function mode to a slower response time mode. Narrow the emitter and receiver distance (Through-beam) Mount the sensor closer to the workpiece (Reflective)
Over Error Incident light level is too high.	All	Enhance the power tuning level. Use a thin-diameter fiber. Widen the emitter and receiver distance (Through-beam) Distance the sensor from the workpiece (Reflective)
Low Error Lo Erro Incident light level is too low.	Tuning other than Maximum Sensitivity Tuning	Decrease the power tuning level. Narrow the emitter and receiver distance (Through-beam) Locate the sensor closer to the workpiece (Reflective)


The adjustment range of smart tuning is approx. 20 to 1/100 times. When selecting Giga Mode as detection function, the range will be approx. 2 to 1/100 times due to the large initial value

Refer to "5 Detailed Settings" to change the powr tuning level

2-4 Minute Adjustment of Threshold Level

1. Press button to adjust the threshold level.






-2-

(3) Convenient Setting Features

(1) Restore from the Incident Level Changed due to Dust and Dirt

1. Hold and buttons for 1 second or longer without a workpiece in the area.





The DPC indicator turns ON


Incident light level setting: The Step 1 incident level is adjusted to the power tuning level. Threshold setting: Not changed. If the value is low, it will be set to the minimum value in which an output is turned ON/OFF correctly.


Perform the procedure with a workpiece in the area for reflective model setting. If the setting is made after position tuning, set both the through-beam model and

Refer to "2-3 Smart Tuning Error" for error displays.

2 Stable Detection Regardless of Incident Level Change due to Dust and Dirt

Perform Smart Tuning. Refer to "2-3 Smart Tuning" Refer to "3 Convenient Setting Features 2. Set the DPC function ON in SET mode.






maximum sensitivity tuning is performed, or the first incident light level of the positioning tuning is low.

The incident light level is corrected to the power tuning level to maintain stable threshold and

	light levels. This provides by dirty sensor head, posi		gardless of the incident level cha erature changes.	nges
Incident Light	Displayed Incident Light Level		Stabilizes the displayed incident level by correcting internal incident level changes.	
Threshold	Interna	al Incident Light Le	The displayed incident I evel decreases and the DPC indicator starts blinking incident level correction	; when
(3) Reset Settin	ngs	Time	possible. Refer to "4-1 Troubles!	

Setting Reset

Initializes all the settings by returning them to the factory defaults.



Caution is required; the output is inverted if button is pressed first. (4) Save or Read Settings

1 Hold on button and then hold button for 3 seconds or longer.

T. Hold button and then hold bu	ш
User Save Function	
Saves the current settings.	
2 Select [SRUE] in 🛱 🗐 and press 🗖 butto	on

 User Reset Function Reads out the saved settings 2.Select [-51:] in and press D buttor

* Press either of UP/DOWN

Smart Tuning is canceled




5 Prevent Mis-operation

Key Lock Function


Disables all button operations. [Lac an] is displayed when the button is pressed.

■ Enable/Cancel (This procedure)



6 Reset Incident Light Level to "0"

Zero Reset Function Changes the incident light level to "0". The threshold level is also shifted accordingly



The zero reset function is canceled when either of the DPC function/differentia function/Smart Tuning is performed.

Maintenance

4-1 Troubleshooting

Troubleshooting

Problem	Cause	Remedy
Blank display	No power supplied or the cable broken	Check the wiring, power supply voltage and capacity. Refer to "4-2 Input/Output Circuit Diagram"
No digital display	Eco mode is ON.	Tum OFF Eco mode. Refer to "5. Detailed Settings". Refer to "5 Detailed Settings".
Sensing/Detection not possible despite the minimum threshold level	Detection set to a small light level mode Dust or dirt influences	The GIGA mode setting enhances the light level and a larger incident level is displayed. LE Refer to "⑤ Detailed Settings".
Incident light level display fluctuation	Dust or dirt, temperature changes or vibration	Use the DPC function to stabilize the incident light level display. All Refer to "③ Convenient Setting Features"
The operation indicator blinking	Mutual interference or other reason	Check the Amplifier Units mounted in a group and turn ON the power again. Refer to "1-2 Mounting Amplifier Unit"
Incident light level displayed in a	The zero reset function is enabled.	Cancel the zero reset function. Befer to "3 Convenient Setting Features"
negative value	The differential function is enabled.	Tum OFF the differential function. ### Refer to "5 Detailed Settings".
Lost tracking of the settings made	-	Reset the settings. Refer to "③ Convenient Setting Features"


Frror Display

- Error Bioplay			
Error Name / Display	Cause	Remedy	
2000 4000	The incident light level has deteriorated due to dust or dirt.	Wipe the dust off the Fiber Unit detection surface or other relevant areas and recover the original incident light level. Then, perform Smart Tuning. Refer to "2-3 Smart Tuning"	
EEPROM Error	Failed internal data read/out	Turn ON the power again. Reset the settings if the error is not corrected. Lack Refer to "③ Convenient Setting Features"	
Lock ON	The key lock function enabled	Cancel the key lock function. Lack Refer to "3 Convenient Setting Features"	
Current Over	Over current flowing to the control output	Check the control output load and adjust it within the rated value. Check for a load short-circuit. Refer to "4-2 Input/Output Circuit Diagram" and "4-3 Ratings and Specifications"	

* The DPC indicator blinks

4-2 Input/Output Circuit Diagram

■ E3X-HD11, E3X-HD6, E3X-HD14 (NPN Type) ■ E3X-HD41, E3X-HD8, E3X-HD44 (PNP Type)



4-3 Ratings and Specifications

	NPN Output	E3X-HD11	E3X-HD6	E3X-HD14	
Model	PNP Output	E3X-HD41	E3X-HD8	E3X-HD44	
Number of	f Control Outputs	1			
Connection Method		Pre-wired Type	Wire-saving Connector Type*1	M8 connector type	
Light Sour	ce (Wavelength)	Red 4-element LED (625 nm)			
Power Su	pply Voltage	12 to 24 VDC ±10%, ripple (p-p) 10% max.			
Power Consumption		Normal: 720 mW max. (current consumption: 30 mA max. at power supply voltage of 24 VDC; 60 mA max. at power supply voltage of 12 VDC) Power-saving ECO: 530 mW max. (current consumption: 22 mA max. at power supply voltage of 24 VDC; 44 mA max. at power supply voltage of 12 VDC)			
Control Ou	utput	Load power supply voltage: 26.4 VDC; NPN/PNP open collector; load current: 50 mA max.; residual voltage: 2 V max.			
Protection	ction Circuits Power supply reverse polarity protection, output short-circuit protection and output reverse polarity protection			rt-circuit protection and	
Maximum	connectable units	onnectable units 16 units			
Mutual Inte	rference Prevention	ntion Possible for up to 10 units *2			
APC (Auto	Power Control)	ntrol) Always ON Receiver side: Incandescent lamp: 20,000 lux max. / Sunlight: 30,000 lux max			
Ambient II	lumination				
Ambient Te	emperature Range	Operating: Groups of 1 to 2 Amplifiers: –25°C to 55°C Groups of 3 to 10 Amplifiers: –25°C to 50°C Groups of 11 to 16 Amplifiers: –25°C to 45°C Storage: –30°C to 70°C (with no icing or condensation)			
Ambient H	lumidity Range	Operating and storage: 35% to 85% (with no condensation)			
Insulation	Resistance	20 MΩ min. (at 500 VDC megger)			
Dielectric S	Strength	1,000 VAC at 50/60 Hz for 1 minute			
Vibration F	Resistance	10 to 55 Hz with a 1.5-mm double amplitude for 2 hours each in X, Y and Z directions			
Shock Res	sistance	500 m/s², for 3 times each in X, Y and Z directions			
Weight (M	lain Unit Only)	Approx. 65 g	Approx. 20 g	Approx. 22 g	
Material		Case: Heat resistant ABS (ABS) / Cover: Polycarbonate (PC)			

*1: Either of E3X-CN11 (Master connector: three core) and E3X-CN12 (Slave connector: single core) can be used. *2: Mutual interference prevention is only possible for up to 6 units, if the E3X-DA-S/MDA sensors applied with power tuning are grouped with this sensor.

*3: The communication and mutual interference prevention functions are disabled when the detection mode is set to Super High-speed Mode

5 Detailed Settings

3. DPC Function

5. Power Tuning Level

Function Selection: [dFLE]

6. Percentage Tuning

7. Differential Function

P-Lu9999

PEr off

diff off

unction Selection: [PL]

PEr

d _iFF

d _iFF

d iFF

d iFF


d IFF

1 🕮

dPc oFF


Hold d button for 3 seconds or longer to enter SET mode.

SET mode provides the function settings described hereafter. The initial display shown



Stable Detection Regardless of Incident Light Level Change

Refer to "3 Convenient Setting Features"



dPc on

A timer value can be set after pressing [7] button when a timer menu (other display than "----") is displayed. Use # | button to set the time. (1 to 9999ms in 1 ms steps; the initial value: 10 ms)

Changing the Target Incident Light Level (Power Tuning Level)

Use button to set the power tuning level. [100 to 9999 in 1 steps; the initial value: 9999]

Refer to "3 Convenient Setting Features"

Detecting Transparent or Small Workpiece


Press button in [PEr on] menu, then use button to set the percentage tuning level. (-99% to 99% in 1% steps; the initial value: -10%)

Refer to "2-3 Smart Tuning"

Detecting Incident Light Level Change Detects if the absolute value of the incident light level change of the set response time is larger than the threshold value. The display shows the change of the incident light level of the set response time in rec

Differential Setting	Response Time		
1	250 µs		
2	500 μs		
3	1 ms		
4	10 ms		
5	100 ms		
Use \biguplus button to specify the response time.			

When the differential function is enabled, the detection function setting is disabled.
Smart tunings except power tuning are disabled The adjustment range of powr tuning is approx. 1 to 1/100 times



Suitability for Use

THE PRODUCTS CONTAINED IN THIS SHEET ARE NOT SAFETY RATED. THEY ARE NOT DESIGNED OR RATED FOR ENSURING SAFETY OF PERSONS, AND SHOULD NOT BE RELIED UPON AS A SAFETY COMPONENT OR PROTECTIVE DEVICE FOR SUCH PURPOSES. Please refer to separate catalogs for OMRON's safety rated products.

OMRON shall not be responsible for conformity with any standards, codes, or regulations that apply to the combination of the products in the customer's application or use of the product.

Take all necessary steps to determine the suitability of the product for the systems, machines, and equipment with which it will be used. Know and observe all prohibitions of use applicable to this product

NEVER USE THE PRODUCTS FOR AN APPLICATION INVOLVING SERIOUS RISK TO LIFE OR PROPERTY WITHOUT ENSURING THAT THE SYSTEM AS A WHOLE HAS BEEN DESIGNED TO ADDRESS THE RISKS, AND THAT THE OMRON PRODUCT IS PROPERLY RATED AND INSTALLED FOR THE INTENDED USE WITHIN THE OVERALL EQUIPMENT OR SYSTEM.

See also Product catalog for Warranty and Limitation of Liability.

